



TOPWIND JACKS - ATWOOD

Part #	Capacity (lbs.)	Description:	Bracket Height Retracted (B) (in.)	Extended (A) (in.)	Caster	Short Foot	Long Foot	Handle	Repair Kit
AT80009	B	1000 Atwood A-Frame Jack, Top Wind	8.6"	23.75"	80259	80260	80261	82700	
AT80401	B	2000 Atwood A-Frame Jack, Top Wind	9"	24.25"	80552	82650	82660	82700	
AT80391	B	5000 Atwood A-Frame Jack, Top Wind	11"	25"	80552	82650	82660	82700	
AT80380	A	5000 Atwood Jack Screw, Top Wind	21.625"	35.75"	80552	82650	82660	82700	

SIDEWIND JACKS - ATWOOD

AT80126	D	1000 Atwood Jack Screw, Side Wind	21.8	35.5	80259	80260	80261		80454
AT81141	D	2000 Atwood Jack Screw, Side Wind	24	38	80552	82650	82660	25526	81480
AT80000	E	1000 Atwood A-Frame Jack, Side Wind	9	24.4	80259	80260	80261		80454
AT87510	E	2000 Atwood A-Frame Jack, Side Wind	8.4	22.4	80552	82650	82660		80465

TOPWIND A-FRAME JACKS - CEQUENT

EA2000	B	2000 Eclipse A-Frame Jack, Top Wind	8	22	CE555	140070	F2000		
140060	B	5000 Eclipse A-Frame Jack, Top Wind	10.8	25.8	CE555	140070	F2000		
155022	C	2000 Hammerblow A-Frame Jack, Top Wind	8.8	23.8	CE555	140070	F2000	500180	500251
155033	C	2000 Hammerblow A-Frame Jack, Top Wind	5.0	20.0		018173		500180	500251
175029	C	5000 Hammerblow A-Frame Jack, Top Wind	10	24.25	CE555	140070	F2000	500180	500223

SIDEWIND A-FRAME JACKS - CEQUENT

155157	F	2000 Hammerblow A-Frame Jack, Side Wind	8.6	21.5	CE555	140070	F2000		
RV2000-0303	G	2000 Fulton A-Frame Jack, Side Wind	8	22	CE555	140070	F2000		

AT80259 1 3/4" ID
AT80552 2" ID

CE555 2 1/16" ID
140075 2 1/16" ID

AT80260 1 3/4" ID
AT82650 2" ID
Foot (Short)

AT80261 1 3/4" ID
AT82660 2" ID
Foot (Long)

140070 2 1/16" ID
Foot (Short) w/ Pin

F2000 2 1/8" ID
Foot (Long) w/ Pin

Special note: **ALL JACKS SOLD WITHOUT MOUNTING BRACKETS** except where noted. Retracted and extended lengths are measured from center mounting plates. Jacks without mounting plates are measured from the handle to the bottom of the jack. When ordering jacks please specify part number for any mounting brackets required.